



built-in ZITA BASE – ZITA PLUS frame heaters

**Drilling of the worktop for built-in: 200 x 133mm
and then refine the 4 screws area**



A TEMPLATE FOR DRILLING THE PANEL IS PRESENT IN THE PACKAGING OF THE MACHINE

WARNING



- Make sure to have a minimum room of 10cm all around the machine inside the worktop
- Make sure that there is a sufficient air vent under the worktop area
- During the working phase the temperature reaches about 80°C near the conveyor . Check if the top of the table can bear such a temperature